

Tornado Protection

Selecting Refuge Areas in Buildings



FEMA



Florida Department of Community Affairs
Tallahassee, FL 32399-2100



About the Cover

The large photograph on the cover shows the remains of a central corridor in the Kelly Elementary School, in Moore, Oklahoma. This extensive damage was caused by one of the tornadoes that struck Oklahoma and Kansas on May 3, 1999. The corridor walls, which consisted of lightweight steel frame members with masonry infill topped by clerestory windows, were unable to withstand the extreme loads caused by lateral and uplift wind forces. As indicated by the inset photograph, which shows a similar corridor in another school, this type of corridor construction is common and creates special challenges for building administrators and design professionals who must identify refuge areas in schools and other buildings.

Contents

Foreword	iii
Introduction	v
Chapter 1: Tornado Profile	1
Chapter 2: Effects of High Winds	7
Wind Effects on Buildings	7
Atmospheric Pressure Changes	8
Debris Impact	9
Selecting Refuge Areas	10
Chapter 3: Case Studies	11
Xenia Senior High School	13
St. Augustine Elementary School and Gymnasium	21
St. Augustine Elementary School Building	22
St. Augustine Elementary School Gymnasium	25
Kelly Elementary School	27

Chapter 4: Selection Procedure	37
Determine the Required Amount of Refuge Area Space	38
Review Construction Drawings and Inspect the Building	39
Assess the Site	42
Example of Refuge Area Selection Process	44
General	44
Required Refuge Area Space	46
Architectural and Structural Characteristics	46
Identifying the Best Available Refuge Areas	51
Verifying the Best Available Refuge Areas	54
Selecting the Best Available Refuge Areas in Other Types of Buildings	55
Mid-Rise and High-Rise Buildings	55
Large Stores and Movie Theaters	55
Chapter 5: Conclusions	57
Information Sources	61

Foreword

Tornadoes cause heavy loss of life and property damage throughout much of the United States. Most schools and other public buildings include areas that offer some protection from this danger, and building administrators should know the locations of these areas.

This booklet presents case studies of three schools that were struck by tornadoes: Xenia Senior High School in Xenia, Ohio; St. Augustine Elementary School in Kalamazoo, Michigan; and Kelly Elementary School in Moore, Oklahoma, which were struck on April 3, 1974; May 13, 1980; and May 3, 1999, respectively. The resulting damage to these schools was examined by teams of structural engineers, building scientists, engineering and architectural faculties, building administrators, and representatives of the architectural firms that designed the buildings. From these and other examinations, guidance has been developed for selecting the safest areas in existing buildings – areas that may offer protection if a tornado strikes – referred to in this booklet as the *best available refuge areas*.

The guidance presented in this booklet is intended primarily to help building administrators, architects, and engineers select the best available refuge areas in existing schools. Building administrators, architects, and engineers are encouraged to apply this guidance so that the number of injuries and deaths will be minimized if a tornado strikes an occupied school.

For the design of shelters in schools yet to be constructed, refer to FEMA publication 361, *Design and Construction of Community Shelters*.

Introduction

What Are “Best Available Refuge Areas”?

The term **best available refuge areas** refers to areas in an existing building that have been deemed by a qualified architect or engineer to likely offer the greatest safety for building occupants during a tornado. It is important to note that, because these areas were not specifically designed as tornado shelters, their occupants may be injured or killed during a tornado. However, people in the best available refuge areas are less likely to be injured or killed than people in other areas of a building.

The likelihood that a tornado will strike a building is a matter of probability. Tornado damage to buildings is predictable. Administrators of schools and other public buildings should have a risk analysis performed to determine the likelihood that a tornado will occur and the potential severity of the event. If a building is determined to be at sufficient risk, the safest areas of the building – areas that may offer protection if a tornado strikes – should be identified. This booklet refers to such areas as the **best available refuge areas**. In many buildings, the best available refuge areas are large enough to accommodate the number of people who normally occupy the building. A qualified architect or structural engineer should assess an existing building and identify the best available refuge areas.

This booklet presents information that will aid qualified architects and engineers in the identification of the best available refuge areas in existing buildings. Architects and engineers who are designing tornado shelters within new buildings may also find this booklet useful, but should refer to *Design and Construction Guidance for Community Shelters* (FEMA 361) for more detailed information. FEMA 361 includes design criteria, information about the performance of specific construction materials under wind and debris impact loads, and examples of construction plans and costs.

The Wind Engineering Research Center at Texas Tech University provided much of the substance of this booklet. Dr. Kishor Mehta of the Center assisted in the preparation and review of the material. Invaluable assistance was provided by the architects and engineers of the buildings presented as case studies and by the school administrators.